


NOTES


- 1 No dimensions to be scaled from this drawing
- 2 All dimensions to be checked on site
- Where discrepancy occurs between specification and drawings the architect must be notified
- 4 COPYRIGHT The contents of this drawing may not be reproduced in whole or in part without the written permission of Fibonacci-Architects Limited

REVISION

| DESCRIPTION | DATE | BY |
|---|--|---|
| First Issue. | 06.02.15 | GS |
| Brickwork setting out adjusted adjacent to Stair 1. Grid revised to reflect current structural drawings. Section lines added. | 15.06.15 | DMM |
| Steel columns and grid revised to reflect current structural engineer's drawings. Possible future tenant's goods lift pit position revised as per current structural engineer's drawing. Stair 2 and core partitions updated. | 20.07.15 | DMM |
| Steel columns revised to reflect current structural engineer's drawings (03.08.15). Windows updated in line with subcontractors drawings and NIA recalculated. Steel and associated grid F2a moved 100mm. | 07.08.15 | СТ |
| Section 11 drawing reference corrected and section reference 16 and 17 added. Steel and associated grid F2a moved back 100mm. Corner area of West service riser omitted. wg.18 widened by 225mm. | 27.08.15 | СТ |
| | First Issue. Brickwork setting out adjusted adjacent to Stair 1. Grid revised to reflect current structural drawings. Section lines added. Steel columns and grid revised to reflect current structural engineer's drawings. Possible future tenant's goods lift pit position revised as per current structural engineer's drawing. Stair 2 and core partitions updated. Steel columns revised to reflect current structural engineer's drawings (03.08.15). Windows updated in line with subcontractors drawings and NIA recalculated. Steel and associated grid F2a moved 100mm. Section 11 drawing reference corrected and section reference 16 and 17 added. Steel and associated grid F2a moved back 100mm. Corner area of West service riser omitted. | First Issue. Brickwork setting out adjusted adjacent to Stair 1. Grid revised to reflect current structural drawings. Section lines added. Steel columns and grid revised to reflect current structural engineer's drawings. Possible future tenant's goods lift pit position revised as per current structural engineer's drawing. Stair 2 and core partitions updated. Steel columns revised to reflect current structural engineer's drawing. Stair 2 and core partitions updated. O7.08.15 drawings (03.08.15). Windows updated in line with subcontractors drawings and NIA recalculated. Steel and associated grid F2a moved 100mm. Section 11 drawing reference corrected and section reference 16 and 17 added. Steel and associated grid F2a moved back 100mm. Corner area of West service riser omitted. |



None of the above is deemed to relieve any contractor of his obligations under all applicable health and safety legislation.



FIBONACCI-ARCHITECTS

Milton Heath House: Westcott Road: Dorking: Surrey: RH4 3NB
Tel: 01306 886289 www. fibonacci-architects.co.uk

MCKAY SECURITIES PLC 73 LONDON ROAD REDHILL

SECOND FLOOR PLAN MARKETING VERSION

DRAWN DMM DRG No CKD CJL DATE Jan 2015 SCALE 1:100 @ A1 1:200 @ A3

D